Audubon Home Inspections
Inspector Turk Schexnayder
Baton Rouge
Date Inspected: 7/13/2025



Picture 1, Baton Rouge Roof Inspection
Photo taken on 7/13/25



Picture 3, Roof Overview
Photo taken on 7/13/25



Picture 4, Section A
Photo taken on 7/13/25



Picture 5, Section C
Photo taken on 7/13/25



Picture 6, Section C
Photo taken on 7/13/25



Picture 7, Upper section A
Photo taken on 7/13/25

Audubon Home Inspections
Inspector Turk Schexnayder
Baton Rouge
Date Inspected: 7/13/2025



Picture 8, Section A, D, & E
Photo taken on 7/13/25



Picture 9, Section D & E
Photo taken on 7/13/25



Picture 10, Lower Section E
Photo taken on 7/13/25



Picture 11, Section E & K
Photo taken on 7/13/25



Picture 12, Section K & F
Photo taken on 7/13/25



Picture 13, Section F
Photo taken on 7/13/25



Picture 14, Section F & H
Photo taken on 7/13/25



Picture 15, Section G & H
Photo taken on 7/13/25



Picture 16, Section H
Photo taken on 7/13/25



Picture 17, Section H
Photo taken on 7/13/25



Picture 18, Section H, I & J
Photo taken on 7/13/25



Picture 19, Section I & J
Photo taken on 7/13/25



Picture 20, Section J
Photo taken on 7/13/25




Picture 21, Section E, K, L & M
Photo taken on 7/13/25



Picture 22, Sections, L, M & N
Photo taken on 7/13/25



Picture 23, Sections M & N
Photo taken on 7/13/25



Picture 24, Cricket behind chimney
Photo taken on 7/13/25




Picture 25, Chimney cap
Photo taken on 7/13/25



Picture 26, Section N
Photo taken on 7/13/25



Picture 27, Section N
Photo taken on 7/13/25



Picture 28, Worn shingles in valley of L & M
Photo taken on 7/13/25




Picture 29, Chimey Cap
Photo taken on 7/13/25



Picture 30, Section N
Photo taken on 7/13/25



Picture 31, Right middle with patch
Photo taken on 7/13/25



Picture 32, Patch near chiney on right & loose gutter
Photo taken on 7/13/25



Picture 33, Section N
Photo taken on 7/13/25



Picture 34, Section N
Photo taken on 7/13/25



Picture 35, Worn shingles section N
Photo taken on 7/13/25



Picture 36, Turtle vent
Photo taken on 7/13/25



Picture 37, Gas appliance vent hood section N
Photo taken on 7/13/25



Picture 38, Sections K, L, M & N
Photo taken on 7/13/25



Picture 39, Sections N & O
Photo taken on 7/13/25



Picture 40, Rear overview
Photo taken on 7/13/25



Picture 41, Sections O, P, & R
Photo taken on 7/13/25



Picture 42, Sections O, P & R
Photo taken on 7/13/25



Picture 43, Valley between P & R
Photo taken on 7/13/25



Picture 44, Patches on section R
Photo taken on 7/13/25




Picture 45, Chimney cap on section R
Photo taken on 7/13/25



Picture 46, Missing shingle cap section R
Photo taken on 7/13/25



Picture 47, Chimney cap on section R
Photo taken on 7/13/25



Picture 48, Chimney cap on section R
Photo taken on 7/13/25



Picture 49, Chimney cap on section R
Photo taken on 7/13/25



Picture 50, Sections D, A, R, S,T, U, & V
Photo taken on 7/13/25



Picture 51, Section S turtle vent and granule loss
Photo taken on 7/13/25



Picture 52, Sections T, U, & V
Photo taken on 7/13/25



Picture 53, Turtle vent Section U
Photo taken on 7/13/25



Picture 54, Sections T, u, V, & W
Photo taken on 7/13/25



Picture 55, Sections V, W, T,R, & X
Photo taken on 7/13/25



Picture 56, Sections W, T, R, X, & B
Photo taken on 7/13/25



Picture 57, Missing step flashing at brick wall
Photo taken on 7/13/25



Picture 58, Front metal roof left side
Photo taken on 7/13/25



Picture 59, Front metal roof middle
Photo taken on 7/13/25



Picture 60, Front metal roof right side
Photo taken on 7/13/25